



Q622 Source Control (Rev 01/08/18)

A supplier specified on the source control drawing is the only acceptable source for this material. If material is purchased from a supplier or distributor, not specified on the drawing, evidence must be provided that the supplier specified on the drawing actually manufactured the material.