

# GENERAL DYNAMICS

## Ordnance and Tactical Systems

### Weapons Systems Supplier Quality Requirements Site 21-Quality – Williston VT / Saco ME

Quality Clause	Revision	Phase In Date
<b>Q221</b>	<b>1</b>	<b>07/28/2020</b>

## Q221–Source Inspection Required

### Requirements

GD-OTS Source Inspection is required prior to shipment from your plant. Unless otherwise directed by the purchase order, supplier is to schedule GD-OTS Source Inspection at least two weeks prior to service need date by contacting your assigned Supplier Quality Engineer. Scheduling issues that are not adequately addressed by your SQE may be resolved by contacting your buyer directly.

Supplier is responsible for the following:

- Providing the source inspector with a clean, well-lit work area conducive to performing source inspection
- Providing the source inspector with all necessary inspection and test equipment
- Providing the source inspector with a complete and legible copy of the relevant TDP
- Providing the source inspector with full access to all necessary documents, records, materials and processes necessary to complete the source inspection.