

<b>1. SQAR Number</b>	SQAR-16
<b>2. SQAR Revision</b>	8
<b>3. SQAR Title</b>	Customer Source Inspection
<b>4. SQAR Detail Description</b>	
<p>Customer Source Inspection is required for the items covered under the Purchase Order prior to shipment from the Supplier's facility. Upon completion of parts and creation of the source package, the Supplier is directed to promptly notify the General Dynamics OTS Quality Engineer or General Dynamics OTS Buyer so that appropriate planning for Customer Source Inspection can be scheduled. The Customer PO must be reviewed for details concerning scheduling of the Customer Source Inspection to include time limit requirements for the notification.</p>	
<b>5. Disclaimer</b>	
<p>The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.</p>	