

1. SQAR Number	SQAR-6
2. SQAR Revision	8
3. SQAR Title	Raw Material Certification or Test Report (Metals, Chemicals, Polymers, etc.)
4. SQAR Detail Description	
<p>The Supplier shall submit a raw material certification or test report for each raw material procured and/or utilized to manufacture the items on the Purchase Order. The certification or report shall list actual values or a range of values of chemical analysis or physical testing required by specification. The certification or report shall include the following at a minimum:</p> <ul style="list-style-type: none">a. Heat Number or equivalentb. Melt, Lot, or Batch numberc. Datad. Specificationse. Origin of manufacturef. Signature of responsible representative of the Supplier, Organization, or Laboratory performing the testing <p>If the testing is not performed by the Raw Material Supplier, the name and address of the company, agency, or organization doing the actual testing shall be included on the certification, along with all identification provided by the testing organization (Lab Accreditation, Scope, etc.).</p>	
5. Disclaimer	
<p>The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.</p>	