

<b>1. SQAR Number</b>	SQAR-7
<b>2. SQAR Revision</b>	0
<b>3. SQAR Title</b>	Certified Test Reports
<b>4. SQAR Detail Description</b>	
<p><b>Certified Test Reports Must Include:</b></p> <p><b>A. Test Data</b></p> <ul style="list-style-type: none"><li>• <i>Actual physical test data</i></li><li>• <i>Actual chemical test data</i></li></ul> <p><b>B. Results of any required non-destructive testing.</b></p> <p><b>C. Test Reports must include Lot, Component and traceability to applicable specifications.</b></p> <p><b>D. All Certified Test Reports must include signature, printed name, and title of the certifying person. Lot/Batch and/or Component Serial Number traceability must be evident throughout all submitted C of Cs.</b></p>	
<b>5. Disclaimer</b>	
<p>The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.</p>	