



Q631 Source Inspection Verification (Rev 01/08/18)

GD-OTS Source Inspection is required prior to shipment from your plant. Unless otherwise directed by the purchase order, Seller is to schedule GD-OTS Source Inspection a minimum of two (2) working days prior to service need date via the Verify, Inc. web site at <https://www.vscnet.com/Suppliers/suppliers.asp>.