

GENERAL DYNAMICS

Ordnance and Tactical Systems

Weapons Systems Supplier Quality Requirements Site 21-Quality – Williston VT / Saco ME

Quality Clause	Revision	Phase In Date
Q20	0	04/02/2019

Q20–Heat and/or Melt Identification

Requirements

All parts and/or material, and applicable documents, must be identified by heat number, heat code, heat lot number of melt number by the seller. Where stamping of individual parts is not practical due to size of shape, the heat number, heat code, heat lot number of melt number shall be stamped on the smallest unit packaged by the seller.