

GENERAL DYNAMICS

Ordnance and Tactical Systems

Weapons Systems Supplier Quality Requirements

Site 21-Quality – Williston VT / Saco ME

Quality Clause	Revision	Phase In Date
Q10	0	04/02/2019

Q10–Source Inspection Verification

Requirements

GD-OTS Source Inspection is required prior to shipment from your plant. Unless otherwise directed by the purchase order, Supplier is to schedule GD-OTS Source Inspection at least 48 hours prior to service need date via the Verify, Inc. web site at <https://www.vscnet.com/Suppliers/suppliers.asp> . Scheduling issues that are not adequately addressed via the Verify eLaunch web site may be resolved by contacting the Verify GD-OTS Field Coordinator at (203) – 638-6319.