

1. SQAR Number	SQAR-14
2. SQAR Revision	8
3. SQAR Title	Surveillance Required
4. SQAR Detail Description	
<p>The items supplied by the Supplier under the Purchase Order are subject to Surveillance by the General Dynamics OTS Quality Engineer (QE), Customer, or other designated representative. The Supplier shall notify the QE or other designated representative prior to the commencement of manufacturing with enough advance notice so that the QE or other designated representative may make arrangements to conduct on-site surveillance of the Supplier's Quality Management System, procedures, records, procurement documents, facilities, and manufacturing processes, and in-process and final inspection/test to verify that the requirements of the Purchase Order are being satisfied if so elected.</p> <p>The Supplier shall provide the representative with reasonable facilities and equipment, and free access to all areas and records, essential to the proper conduct of (as applicable) design, development, manufacture, inspection, testing, and packaging and shipping of the procured items.</p>	
5. Disclaimer	
<p>The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.</p>	