

1. SQAR Number	SQAR-21
2. SQAR Revision	8
3. SQAR Title	PAL 128 Without Source Inspection
4. SQAR Detail Description	
The Supplier shall provide a PAL 128 for the items to be delivered under the Purchase Order along with any additional documentation required by the PO. The supplier shall not ship without a signed PAL 128, and the signed PAL 128 must be included with the shipment. PAL 128 Page-2 is not required.	
5. Disclaimer	
The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.	