GENERAL DYNAMICS

Ordnance and Tactical Systems Niceville, FL

1.	SQAR Number	SQAR-26
2.	SQAR Revision	8
3.	SQAR Title	Process Flow and PFMEA
4.	4. SQAR Detail Description	
	The Supplier shall submit a Process Flow and Process Failure Mode and Effects Analysis (PFMEA) in the Supplier's format for	
	the items to be delivered under the Purchase Order. The Process Flow and PFMEA shall be submitted to the General	
	Dynamics OTS Buyer for approval prior to FAI or first source inspection submittal. Assistance may be provided to the Supplier	
	by General Dynamics OTS if requested or if General Dynamics OTS sees a need to facilitate or participate. A template is	
	located in PAL 128, Data/Source Inspection Request/Approval Workbook.	
5. Disclaimer		
	The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within	

The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.