

1. SQAR Number	SQAR-13
2. SQAR Revision	10
3. SQAR Title	Source Inspection Required
4. SQAR Detail Description	
<p>The items supplied by the Supplier under the Purchase Order are subject to Source Inspection by the GD-OTS Quality Engineer (QE) or other designated representative. The Supplier shall notify the QE or other designated representative at least 5 business days prior to the expected source inspection; PAL 128 and Page-2 submitted. The Supplier may not ship any items without authorization through an approved PAL 128 form signed by the QE or other designated representative, and it must be included with the shipment. The Supplier must have available, at the time of presentation, a complete Source Inspection package. The Supplier shall provide the QE or other designated representative with reasonable facilities and equipment and free access to all areas and records essential to the proper conduct of source inspection of the procured items. The performance of a source inspection, whether on-site or not (Desk Audit), does not relieve the Supplier of any responsibility for the determination of conformance of the items to the contracted requirements.</p>	
5. Disclaimer	
<p>The following Supplemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between the General Supplier Quality Assurance Requirements document, PAL 164, and a SQAR flowdown, the SQAR will always supersede. Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.</p>	