GENERAL DYNAMICS Ordnance and Tactical Systems

Ordnance and Tactical Systems Anniston,AL

1.	SQAR Number	SQAR-8	
2.	SQAR Revision	0	
3.	SQAR Title	Heat Treat Services	
4.	4. SQAR Detail Description		
	Heat Treat Services Require the Following Information:		
	 For heat treat services, temperatures and process used and actual hardness results as required by applicable specifications must be defined on the certification. 		
	All services must be certified to meet all applicable standards, including those incorporated by reference.		
	 All C of Cs for Heat Treat services must include signature, printed name, and title of the certifying person. Lot/Batch and/or Component Serial Number traceability must be evident throughout all submitted C of Cs. 		
5.	Disclaimer		
	The following Sup	plemental Quality Assurance Requirement (SQAR) clause is a requirement when specified by number within	
	the Request for Quote (RFQ), Purchase Order (PO), or Quality Assurance Document (QAD). In the event of conflict between		
	the General Supplier Quality Assurance Requirements document and a SQAR flowdown, the SQAR will always supersede.		
	Flowdown of this SQAR to sub-tier suppliers is required to ensure final product compliance.		